hazardel	Who might be harmed and how?	What a doing?	re you already	What further action is necessary?	Action by who?	Action by when?	Done
			Car park surface maintained to be as even as	■□Surface to be inspected regularly and repaired as necessary.	Chairman	Inspect three- monthly	2 August 2017 and every three months
Slips, trips and falls Eg uneven surface of car park, cleaning floors etc.	Users of the hall and car park may suffer injuries such as fractures or bruising if they slip, eg on spillages or trip over objects.		possible. Parking spaces for visitors with disabilities available next to hall entrance. Good lighting in car park and all rooms and corridors in hall. Users know (through hire agreement) to clear up spillages immediately and know where equipment for this is kept. Mats at entrances to stop rain water being	Regular	Secretary Nominated member of	October 2016	October 2016
			carried in. No storage in corridors. No trailing electrical leads/cables.	inspections on proforma	member of Management Committee	Monthly	October 2016 and on going
Eg changing light bulbs, cleaning windows, putting up	Anyone working at any height could suffer injuries, possibly very serious ones, should they fall.		Appropriate, commercial stepladder securely stored and available for use. Hall users know (through hire agreement) that	■ Print copies of HSE guidance on safe use of stepladders and make available to those who may use stepladder. Attached on noticeboard	Secretary	October 2106	October 2016

St Piran's Hall Date of risk assessment: March 2020

decorations		•	■□Put in place			
etc.		*	system for	Chairman		
		using the	0		Annually	
		stepladder safely.	condition of			
		Hall committee	stepladder.			
		members and	Consider			
		cleaner know	implications for	C	As	
		how to use the	work at height of			On
		stepladder safely.	any future	Secretary	needed	going
			alterations to the			
			hall.			

What are the hazards?	Who might be harmed and how?	What a doing?	re you already	What further action is necessary?	Action by who?	Action by when?	Done
	Pedestrians could suffer serious injury if struck by cars entering/leaving car park or moving in it.		Entrance/exit to car park clearly marked. For large events, parking controlled by	mph speed limit in car	Agreed by Management Committee	21/1/2019	21/1/19
Vehicle movement			marshals wearing high- visibility vests. Car park well lit. Major works takes place at times when hall not in use or users advised	U	Lettings Secretary	1/4/18	Done and ongoing
	The cleaner, and others cleaning, risk skin problems, eg dermatitis and eye damage, from direct contact with cleaning chemicals. Vapour may cause breathing problems.		Mops, brushes and strong rubber gloves provided. Cleaning products marked 'irritant' replaced with milder alternatives. Cleaner trained to use products safely, eg follow instructions on	■ Cleaner reminded to check for dry, red or itchy skin on her hands and, if finding any, to go to doctors for advice and to tell the secretary to the management committee.	Secretary	2015	2015

		the label, dilute properly and never transfer to an unmarked container. Cleaning products stored securely.				
		correctly installed by qualified electrician, and inspected regularly.	■ Advise hall users through the hire agreement where the fuse box is and how to switch supply off in an emergency.	Lettings Secretary	April 2018	
Electricity	Users risk electric shocks or burns from faulty equipment or installation.	 electrician. Safety plugs in sockets. Portable equipment checked for visual signs of damage before use. Hall users know they are responsible for any equipment 	■ Remind users that portable equipment should be considered for PAT and any unsafe equipment should be marked and taken out of use.	Secretary	2015 Since 2018 a PAT session open to users has been organised in Feb 2020	2015
eaumment	Users could be injured by collapsing stacks.	chairs carefully so that	■□Notice near storage areas to encourage safe stacking	Secretary	2015	19/10/16
handling	Users may suffer back pain if they try to lift objects that are too heavy or awkward.	 Trolleys available to move heavy equipment and users know where they are kept. 	Trolley available in store	Chairman	19/10/16	19/10/16

	What are ou already loing?	Action by who?	Action by when?	Done
--	----------------------------------	-------------------	--------------------	------

Ashestos	tibres are	Visual check undertaken	 Damaged asbestos to be removed by specialist contractors. If hall is ever demolished/refurbished, asbestos should first be removed by specialist contractors. If hall is ever demolished/refurbished, asbestos should first be removed by specialist 	19/1016/
Fire	could suffer fatal injuries from	done, annual	(hairman)	July 2017

Assessment review date: 21/3/20

Reviewed in March 2020 agreed by St Piran's Hall Management Committee